



Inspection Report

Report Date 28/10/2011

Company HMP HOME INSPECTIONS

Customer MABEL BROWN

Address 123 MAIN ST.

Site Address

Thermographer STEVE POCKETT

Contact Person





Image and Object Parameters

Text Comments

Camera Model	FLIR B300
Image Date	20/10/2011 6:26:51 PM
Image Name	IR_0067.jpg
Emissivity	0.95
Reflected apparent temperature	27.0 °C
Object Distance	2.0 m

Description

Kitchen ceiling. Evidence of water leaking from upper ensuite bathroom. Darker areas show water pooling on the drywall.

Recommended task is to remove water damaged drywall to investigate suspected void in plumbing. Make necessary repairs.